

DEPARTMENT OF THE NAVY

COMMANDER
NAVY REGION HAWAII
850 TICONDEROGA ST STE 110
JBPHH, HAWAII 96860-5101

5090 Ser N45/037 February 14, 2023

Sent via email

Mr. Gaudencio Lopez, P.E., Chief Hawaii State Department of Health Environmental Management Division Safe Drinking Water Branch 2385 Waimano Home Road Uluakupu Building 4 Pearl City, HI 96782

Dear Mr. Lopez:

SUBJECT: PUBLIC WATER SYSTEM NO. 430 PACIFIC MISSILE RANGE FACILITY (PMRF)
WATER SYSTEM SANITARY SURVEY REPORT RESPONSE

The Navy received the Report of Sanitary Survey from the Hawaii Department of Health Safe Drinking Water Branch on January 17, 2023 regarding DOH's sanitary survey of the PMRF water system conducted on September 28, 2022. The Navy appreciates the assistance and technical guidance provided by your staff during the survey.

The sanitary survey identified one significant deficiency and made multiple recommendations which the Navy has reviewed. The plan of action to address the significant deficiency and ongoing actions for each recommendation are provided in Enclosure 1. As requested, the Navy will continue to address each of DOH's findings in a timely manner, to the extent that resources and operations allow.

Should you have any questions regarding this matter, please contact Sara Lin at (808) 471-4676.

Sincerely,

SHERRIR. ENG

Director

Regional Environmental Department

By direction of the

Commander

Enclosure: Table of Navy Actions in Response to DOH PMRF Sanitary Survey Report dated January 11,

2023

Copy to: Commanding Officer, Naval Medical Clinic, Joint Base Pearl Harbor-Hickam (Preventive Medicine Department)

	SIGNIFICANT DEFICIENCY	CORRECTIVE PLAN OF ACTION	РНОТО	STATUS
1	Mana Well – Recurring significant deficiency. Seal for direct opening to aquifer needs to be below pumps.	Navy is working to develop a way ahead and has requested to reopen discussions with DOH to identify acceptable alternative solutions.		Ongoing

	RECOMMENDATION	NAVY'S PLAN OF ACTION	РНОТО	STATUS
1	Bldg 394 – provide secondary containment for sodium fluoride drum.	Secondary containment procured for sodium fluoride drum. See photo.	SU CORIDE	Complete
2	Bldg 394 – provide Safety Data Sheet on site wherever chemicals are stored.	Will address. Navy to provide SDS onsite.		Ongoing

	RECOMMENDATION	NAVY'S PLAN OF ACTION	РНОТО	STATUS
3	Bldg 394 – address corrosion on valve of water supply line.	Valve replaced. See photo.		Complete
4	Tank 824 – remove wasp nests for operator access and safety.	Will address. Navy to initiate pest removal.		Ongoing

	RECOMMENDATION	NAVY'S PLAN OF ACTION	РНОТО	STATUS
5	Tank 820 – secure vent hatch with lock.	Locking mechanism added. See photo.		Complete

	RECOMMENDATION	NAVY'S PLAN OF ACTION	РНОТО	STATUS
6	Tank 820 – significant rusting around ladder at base of tank. Inspect, refurbish, or replace.	See photo.		Complete
7	Bldg 821 – provide secondary containment for sodium fluoride drum.	Will address. Navy to procure secondary containment for NaF drum.		Ongoing
8	Bldg 821 – provide Safety Data Sheet on site wherever chemicals are stored.	Will address. Navy to provide SDS onsite.		Ongoing
9	Hydro-pneumatic Tank 829 – address corrosion on bolts.	Navy to request funding to inspect, refurbish, or replace.		Ongoing